



Product Description

BERGER METAL PRIMER ZINC CHROMATE (Red/ Yellow Oxide) is a Zinc Chromate pigmented Alkyd primer for use on metal substrates in mild or moderate environments.

Design Use

Areas of Use: Interior/ Exterior

Substrate: Steel, iron. For zinc and aluminium, see recommendation on surface preparation

Compatible Coatings: Berger's Alkyd Enamels - 404 Industrial Enamel, Marine Enamel

Physical Data

Finishes: Matte

Colour: Red Oxide, Yellow Spread Rate: Not applicable Drying Time: To touch: 15 mins To handle: 1 hr.

To recoat: 4 hrs.

Gloss Levels: Matte

Application Data

Recommended airless spray with constant agitation to avoid zinc dust from settling.

BRUSH ROLLER For small area touch up. Apply during dry conditions.

Minimum Temperature: 40°F (4°C) **Maximum Temperature:** 130°F (54°C)

Minimum Humidity 0%

Maximum Humidity 95% Surface Temperature 40°F to 130°F (4°C to 54°C)

Coverage: 300 sq. ft/gallon (6.13 sq. metre/litre)

Drying Time: To touch: 15 mins

To handle: 1 hr.

Maximum Recoat Time: 4 hrs.

Additional Information

Thinner: Berger Reducer No. 5 (Berger Economy Grade Lacquer thinner can be use to clean

equipment)

Storage Instruction: Store indoors Temperature: -40° - 110°C (4° - 43°C Humidity: -0 -90%)

Flash Point: Lab to provide.

Shelf Life: 24 Months (Agitate periodically to prevent settling)

Pack Size: Not applicable Pot Life: 8 hours

Surface Preparation

IMMERSION- Abrasive Blast Clean to near white metal SSPC SP10.

Blast profile: 1 - 3 mils (25 to 75 microns) Non-Immersion - Commercial blast to SSPC -SP6 and blast profile 1 - 3 mils

(25 to microns)

WATER IMMERSION SERVICE: Prepare steel as above and over coat with Berger Hibuild Epoxy

MIXING: Power mix both BASE and CONVERTER, combine 4:1 ratio by volume.

BASE: CONVERTER and power mix



Health and Safety

READ INSTRUCTIONS CAREFULLY BEFORE USE

Do not take internally.

Liquid paint and vapours may cause irritation.

Use only with adequate ventilation.

To ensure the entry of fresh air, open all windows and doors. If headache or dizziness is experienced use respiratory protection or leave area for fresh air.

Avoid contact with skin and eyes.

First Aid

Ingestion: Do not induce vomiting. Get medical attention immediately.

If excessive exposure symptoms are experienced, leave area to obtain fresh air. Inhalation:

If difficulty continues, seek immediate medical attention.

Eye Contact: Flush immediately with water for at least 15 minutes.

Skin Contact: Wash thoroughly with soap and water.

Recommended Paint Solutions Step 1



Apply 1 or 2 coats BERGER Metal Zinc **Chromate Red or Yellow** to properly prepared surface.

Step 2









BERGER Metal Zinc Chromate Red or Yellow is a great primer under Berger 404 Gloss and Semi-Gloss, RustPro Premium Anti-Rust Gloss and Magicote Gloss Paints

Contact Us



Berger Paints Barbados Ltd. Exmouth Gap, Brandons, St. Michael

Bridgetown, Barbados, W.I. BB12069 Tel: +1-246-425-9073 Fax: +1-246-228-0866

Email: info@bergeronline.com

Berger Paints Jamaica Ltd.

256 Spanish Town Road P.O. Box 8, Kingston 11, Jamaica Tel: +1-876-923-6226 Fax: +1-876-923-5129 Email: bergerja_marketing@bergeronline.com Berger Paints Trinidad Ltd.

P.O. Box 546, 11 Concessions Road. Sea Lots, Port Of Spain, Trinidad Tel: +1-868-623-2231 Fax: +1-868-623-1682





